Oil Field Environmental Incident Summary

Responsible Party: QEP ENERGY COMPANY
Well Operator: QEP ENERGY COMPANY
Well Name: CENTRAL TANK BATTERY 2-16X

Field Name: GRAIL Well File #:

Date Incident:6/11/2015Time Incident:15:00Facility ID Number:218973-01County:MCKENZIETwp:150Rng:95Sec:16Qtr:NE

Location Description:

Submitted By: Jerry Reinisch Received By:

Contact Person: Jerry Reinisch

1050 17TH ST STE 500 DENVER, CO 80265

General Land Use: Pasture Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.8 MileDistance Nearest Water Well:0.8 Mile

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units
Oil 75 Barrels 75 Barrels 75 barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 3/1/2016 Clean Up Concluded: 6/16/2015

Risk Evaluation:

medium, because of the amount of oil released.

Areal Extent:

Potential Environmental Impacts:

No impacts to surface or groundwater. Release was cleaned up immdediately.

Action Taken or Planned:

Additional operator training and supervision. The unit was shut in and the area remediated with vac trucks.

Wastes Disposal Location: The fluids were transferred back through the re-cycle system and the

solids were transported to Secure Energy.

Agencies Involved: BLM

Updates

Date: 6/15/2015 Status: Reviewed - Assigned to Other Agency Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to treater leak, remained on location within the diking, according to the report. NDIC retains oversight.